Rob Watson

FILE

Rockford
Cold Formed Products

Rockford Products Corporation
707 Harrison Avenue
Rockford, Illinois 61108-7197
(815) 397-6000
Easy Link 910997-7453

March 19, 1986

2010300031 - WINNEBAGO
ROCKFORD / ROCKFORD
PROD # 3

Illinois Environmental Protection Agency
Region 1
4302 North Main Street
Rockford, Illinois 61103

Attention: Mr. Harris Chien
Manager

Dear Mr. Chien:

ROCKFORD PRODUCTS CORPORATION is submitting the following information requested from IEPA meeting held in your office on January 14, 1986 at 2:00 P.M.

After a telephone call to Rob Watson, on January 15, 1986, regarding the surveys for "Certification Regarding Potential Releases From Solid Waste Management Units (Closure Plan Review)" * 8 separate form surveys were completed and sent to Lawerence Esteps office in Springfield, Illinois on January 28, 1986.

* LOG C-191

A revised air permit application was sent to Bharat Mathur on January 17, 1986, for (4) Detrex Degreasers. Permit to operate the (4) Detrex Degreasers was granted on February 24, 1986.

A ground water monitoring plan was prepared for ROCKFORD PRODUCTS CORPORATION submitted herewith by M. Rapps Assoc., Inc. in Springfield, Illinois.

Also a roof storm water plan was developed to minimize contaminents entering the seepage pit submitted herewith by Larry Hammond - Industrial Consultant.

ROCKFORD PRODUCTS CORPORATION has earnestly tried to answer all requirements from the January 14, 1986 meeting, and will continue to work closely with your office until all problems are resolved.

Sincerely yours,

ROCKFORD PRODUCTS CORP.

Harold W. Naill
Vice President of Mfg.

HWN/nc

ROOF STORM WATER PLAN - 3-19-86

If as the result of the proposed ground water monitoring plan, it is ultimately determined that storm water run-off from roof of Plant #3 is causing contamination of the seepage pit, than ROCKFORD PRODUCTS CORPORATION will remedy that situation by one of several possible alternatives. Alternatives currently being considered are:

a. Make quarterly checks of velocity and exhaust emissions from discharge stacks.

b. Raise exhaust stacks from degreasers 20 feet. Two significant improvements should take place.

1. More condensation of 1,1,1 Trichlorethane will occur in the stack and be recaptured for reuse.

2. The added height of stacks will allow remaining stack emissions to stay in the atmosphere.

c. Modify internal cooling coils to reduce emission stack temperature which in turn will reduce stack emissions up to 40%.

d. To further investigate a proven European technology, using refrigeration chilling coils in the exhaust stacks, where emission reduction rates can be reduced by as much as 90%.

e. Lab analysis of seepage pit water, and samples from test wells will be sent to R. E. Wright Assoc., Inc. for study of volatile organic compounds, and the removal of v.o.c. by using an air stripping tower. If acceptable removal rates can be reached. ROCKFORD PRODUCTS CORPORATION must make a decision to use this process, or one of the following.

II. Work with the Public Works Department - City of Rockford to develop a plan for installation of a storm sewer at approximately the 2800 block on East side of Kishwaukee Street, so that, storm water run-off from roof of ROCKFORD PRODUCTS CORPORATION - Plant #3 could enter, using controlled run-off procedures, and a N.P.D.E.S. Permit.

III. Develop a plan with the Public Works Department - City of Rockford for roof run-off water that will enter into a box culvert running parallel to East property line of ROCKFORD PRODUCTS CORPORATION using controlled run-off procedures and a N.P.D.E.S. Permit.

IV. To investigate with the Public Works Department - City of Rockford, if feasible to use a drainage ditch running from the West side of ROCKFORD PRODUCTS CORPORATION property to Rock River. After topography survey is made, a cost analysis should be made to clean out bottom of ditch for 300 to 500 feet West of ROCKFORD PRODUCTS CORPORATION, so that, roof drainage will properly flow into drainage ditch.

After confirmation of lab reports for present volatile organic compounds, this may prove that a controlled system for run-off waters will be sufficient.

Harold W. Naill
Vice President of
Manufacturing

HWN/rc

Rockford Products Corporation

Plant No. 3

Groundwater Monitoring Plan

M. Rapps Associates, Inc.
ENVIRONMENTAL ENGINEERING
2387 WEST MONROE, SUITE 123, SPRINGFIELD, ILLINOIS 62704 — (217) 787-2118

Rockford Products Corporation

Plant No. 3

Groundwater Monitoring Plan

Background

Rockford Products Corporation's (RPC) plant No. 3 is located at 707 Harrison Avenue, Rockford, Illinois. The manufacturing facility, which utilizes various metal finishing processes in the course of its operations, is situated in the heavily industrialized Southeast sector of Rockford. Most of Rockford's industrial activity, principally metal finishing and fabricating, is housed in this part of the city. Adjacent property to the East contains abandoned rail lines, a construction company storage yard, and an auto salvage yard. A conglomeration of heavier manufacturing plants, material suppliers, etc., exists farther to the East, following the Harrison Avenue corridor for several miles. Similar activity exists to the West and Northwest of the plant, including an abandoned landfill, a large foundry, a steel drum reclaimer, and various other industrial operations. Scattered pockets of residential housing exist throughout these areas, in all directions from the plant. The plant site and surrounding areas are shown in Figure 1 in the attachments.

RPC plant No.3 is situated on relatively flat ground that has little natural drainage. As a consequence, storm water from plant buildings and parking areas, joined by drainage from properties to the East, tends to accumulate and pond on plant property. Attempts to divert this water to a municipal storm sewer were unsuccessful

and, as such, plant officials have found it necessary to design an on-site remedy. That solution consists of drainage features which gather and divert storm water to a dug pond or seepage pit. The main body of the seepage pit consumes a surface area of approximately one acre. Its maximum depth near the center is approximately eleven feet.

A permit to use the seepage pit was issued by the Illinois Environmental Protection Agency's (IEPA) Division of Water Pollution Control (DWPC) on March 21, 1984. That permit contains a special condition requiring installation of three monitoring wells subject to quarterly water quality testing. Water quality parameters to be monitored include Specific Conductance (S.C.), Chemical Oxygen Demand (COD), Total Organic Carbon (TOC), and Total Organic Halogens (TOX).

Requisite monitoring points were installed in January, 1985. They consist of three two inch I.D. screw coupled PVC wells with slotted screens, each set at a depth of 35.0'. Well screen sections are ten feet in length and intercept the water table. In the second quarter subsequent to well installation, each well and the seepage pit (and attendant storm water ditches) were sampled for an extensive analysis. Results are:

Culvert and Pond Samples (5-8-85)

Sample Locations

Organic Contaminant	S.W. Culvert	S.E. Culvert	Pond	Mean	Variance
1,1,1-Trichloroethane	25 ppb	81 ppb	27 ppb	44.3	672.8
1,1-Dichloroethane	5 ppb	15 ppb	5 ppb	8.3	22.2
1,1-Dichloroethylene	10 ppb	31 ppb	<5(2.5 ppb)	14.5	145.5
1,2-t-Dichloroethylene	7 ppb	16 ppb	<5(2.5 ppb)	8.5	31.5
Trichloroethylene	15 ppb	48 ppb	12 ppb	25	266

Sediment Samples (5-8-85)

Parameter	Sample Location: S.E. Sediment	S.E. Sediment @ 12"
Arsenic	< 0.001 ppm	< 0.001 ppm
Barium	0.54 ppm	0.54 ppm
Cadmium	0.014 ppm	0.005 ppm
Chromium	0.025 ppm	0.024 ppm
Lead	0.03 ppm	0.05 ppm
Mercury	< 0.001 ppm	< 0.001 ppm
Selenium	< 0.005 ppm	< 0.005 ppm
Silver	< 0.001 ppm	< 0.001 ppm

NOTE: The above are analyses of "leachate" based on the EPA EP TOX test. Organic analyses of sediment samples revealed no contamination above detection limits; typically 50 ppb.

Groundwater Samples

Organic Contaminant (5-8-85)	Sample Location: W-1	W-2	W-3	Mean	Variance
1,1,1 Trichloroethane	39 ppb	199 ppb	43 ppb	93.6	5550.2
Trichloroethylene	7 ppb	<5(2.5 ppb)	452 ppb	153.8	44,455
Indicator Parameter (1-3-86)					
S.C.	550 umhos	550 umhos	550 umhos	550	-
TOC	49 ppm	8.6 ppm	2.2 ppm	19.9	429.3
TOX	87 ppb	<5(2.5 ppb)	<5(2.5 ppb)	30.6	1586.7

These preliminary analyses indicate the presence of organic contamination in both the pond and in the groundwater; with the solvents 1,1,1-Trichloroethane and Trichloroethylene being common to both. While a greater number of organic contaminants were identified in the pond, the greatest levels of contamination are apparently in the groundwater. Inorganic analyses on sediment samples by the EP-toxicity test method do not reveal metal concentrations out of the ordinary. The same is true of organic analyses of sediment samples, and of indicator parameter analyses of the groundwater.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



Scale: 1" = 2000'

Figure 1.


ROCKFORD AREA
PIEZOMETRIC SURFACE (Feet-MSL)
(1948)
Scale: 1" = 4000'
W15
W18
W4
W11
W38
W7
W7A
W9
W9A
W13
W10
W6
W16
W14
W35
W19
W36
W28
DISTRICT III
DISTRICT IV
ROCKFORD PRODUCTS CORP.
LEGEND
— Sandstone Well
— Sand & Gravel Well

Figure 6.

Equalab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

5-17-05

ANALYTICAL REPORT

Mr. Steve Reid
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61107

8 May 1985
Sample No. 34388

Sample Description: #1 S.W. Culvert

Date Received: 4/29/85

VOLATILE COMPOUNDS

ug/l	Compound	ug/l	Compound
<100	Acrolein	7.	1,2-Trans-Dichloroethene
<100	Acrylonitrile	<5	1,2-Dichloropropane
<5	Benzene	<5	1,3-Dichloropropene
<5	Carbon Tetrachloride	<5	Ethylbenzene
<5	Chlorobenzene	<10	Methylene Chloride
<5	1,2-Dichloroethane	<20	Methyl Chloride
25.	1,1,1-Trichloroethane	<20	Methyl Bromide
5.	1,1-Dichloroethane	<10	Bromoform
<10	1,1,2-Trichloroethane	<5	Dichlorobromomethane
<10	1,1,2,2-Tetrachloroethane	<10	Chlorodibromomethane
<20	Chloroethane	<5	Tetrachloroethene
<50	2-Chloroethylvinyl Ether	<5	Toluene
<5	Chloroform	15.	Trichloroethene
10.	1,1-Dichloroethene	<20	Vinyl Chloride
<5	Xylene	<5	1,2-Dichlorobenzene
		<5	1,3-Dichlorobenzene
		<5	1,4-Dichlorobenzene

William H. Mottashed
William H. Mottashed
Division Manager

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Steve Reid
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61107

8 May 1985
Sample No. 34389

Sample Description: #2 S. EAST CULVERT

Date Received: 4/29/85

VOLATILE COMPOUNDS

ug/l	Compound	ug/l	Compound
<100	Acrolein	16.	1,2-Trans-Dichloroethene
<100	Acrylonitrile	<5	1,2-Dichloropropane
<5	Benzene	<5	1,3-Dichloropropene
<5	Carbon Tetrachloride	<5	Ethylbenzene
<5	Chlorobenzene	<10	Methylene Chloride
<5	1,2-Dichloroethane	<20	Methyl Chloride
81.	1,1,1-Trichloroethane	<20	Methyl Bromide
15.	1,1-Dichloroethane	<10	Bromoform
<10	1,1,2-Trichloroethane	<5	Dichlorobromomethane
<10	1,1,2,2-Tetrachloroethane	<10	Chlorodibromomethane
<20	Chloroethane	<5	Tetrachloroethene
<50	2-Chloroethylvinyl Ether	<5	Toluene
<5	Chloroform	48.	Trichloroethene
31.	1,1-Dichloroethene	<20	Vinyl Chloride
<5	Xylene	<5	1,2-Dichlorobenzene
		<5	1,3-Dichlorobenzene
		<5	1,4-Dichlorobenzene

William H Mottashed

William H. Mottashed
Division Manager

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Steve Reid
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61107

8 May 1985
Sample No. 34390

Sample Description: #3 S.E. Pond

Date Received: 4/29/85

VOLATILE COMPOUNDS

ug/l	Compound	ug/l	Compound
<100	Acrolein	<5	1,2-Trans-Dichloroethene
<100	Acrylonitrile	<5	1,2-Dichloropropane
<5	Benzene	<5	1,3-Dichloropropene
<5	Carbon Tetrachloride	<5	Ethylbenzene
<5	Chlorobenzene	<10	Methylene Chloride
<5	1,2-Dichloroethane	<20	Methyl Chloride
27.	1,1,1-Trichloroethane	<20	Methyl Bromide
5.	1,1-Dichloroethane	<10	Bromoform
<10	1,1,2-Trichloroethane	<5	Dichlorobromomethane
<10	1,1,2,2-Tetrachloroethane	<10	Chlorodibromomethane
<20	Chloroethane	<5	Tetrachloroethene
<50	2-Chloroethylvinyl Ether	<5	Toluene
<5	Chloroform	12.	Trichloroethene
<5	1,1-Dichloroethene	<20	Vinyl Chloride
<5	Xylene	<5	1,2-Dichlorobenzene
		<5	1,3-Dichlorobenzene
		<5	1,4-Dichlorobenzene

William H. Mottashed

William H. Mottashed
Division Manager

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Steve Reid
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61107

8 May 1985
Sample No. 34391

Sample Description: #4 S.E. Sediment

Date Received: 4/29/85

VOLATILE COMPOUNDS

ug/Kg	Compound	ug/Kg	Compound
<1000	Acrolein	<50	1,2-Trans-Dichloroethene
<1000	Acrylonitrile	<50	1,2-Dichloropropane
<50	Benzene	<50	1,3-Dichloropropene
<50	Carbon Tetrachloride	<50	Ethylbenzene
<50	Chlorobenzene	<100	Methylene Chloride
<50	1,2-Dichloroethane	<200	Methyl Chloride
<50	1,1,1-Trichloroethane	<200	Methyl Bromide
<50	1,1-Dichloroethane	<100	Bromoform
<100	1,1,2-Trichloroethane	<50	Dichlorobromomethane
<100	1,1,2,2-Tetrachloroethane	<100	Chlorodibromomethane
<200	Chloroethane	<50	Tetrachloroethene
<500	2-Chloroethylvinyl Ether	<50	Toluene
<50	Chloroform	<50	Trichloroethene
<50	1,1-Dichloroethene	<200	Vinyl Chloride

William H. Mottashed

William H. Mottashed
Division Manager

aqualab inc.
3548 35th St.
Rockford IL 61109
815 874-2171

ANALYTICAL REPORT

Mr. Steve Reid
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61107

8 May 1985
Sample No. 34391

Date Received: 4/29/85 1045 S.E. SEDIMENT

E.P.TOXICITY

Arsenic	<0.001	ppm
Barium	0.54	ppm
Cadmium	0.014	ppm
Chromium	0.025	ppm
Lead	0.03	ppm
Mercury	<0.001	ppm
Selenium	<0.005	ppm
Silver	<0.001	ppm

William H. Mottashed
William H. Mottashed
Division Manager

aqualab inc.
35-48 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Steve Reid
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61107

8 May 1985
Sample No. 34392

Sample Description: #5 S.E. Sediment 12" Below Surface

Date Received: 4/29/85

VOLATILE COMPOUNDS

ug/Kg	Compound	ug/Kg	Compound
<1000	Acrolein	<50	1,2-Trans-Dichloroethene
<1000	Acrylonitrile	<50	1,2-Dichloropropane
<50	Benzene	<50	1,3-Dichloropropene
<50	Carbon Tetrachloride	<50	Ethylbenzene
<50	Chlorobenzene	<100	Methylene Chloride
<50	1,2-Dichloroethane	<200	Methyl Chloride
<50	1,1,1-Trichloroethane	<200	Methyl Bromide
<50	1,1-Dichloroethane	<100	Bromoform
<100	1,1,2-Trichloroethane	<50	Dichlorobromomethane
<100	1,1,2,2-Tetrachloroethane	<100	Chlorodibromomethane
<200	Chloroethane	<50	Tetrachloroethene
<500	2-Chloroethylvinyl Ether	<50	Toluene
<50	Chloroform	<50	Trichloroethene
<50	1,1-Dichloroethene	<200	Vinyl Chloride

William H. Mottashed

William H. Mottashed
Division Manager

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Steve Reid
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61107

8 May 1985
Sample No. 34392

Date Received: 4/29/85 1045 S.E. Sediment 12" Below Surface

E.P.TOXICITY

Arsenic	<0.001	ppm
Barium	0.54	ppm
Cadmium	0.005	ppm
Chromium	0.024	ppm
Lead	0.05	ppm
Mercury	<0.001	ppm
Selenium	<0.005	ppm
Silver	<0.001	ppm

William H. Mottashed
William H. Mottashed
Division Manager

aqua ab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Chris Berndt
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61109

3 January 1986
Sample No. 37825

SAMPLE DESCRIPTION: W1
P.O. 82634
Date Taken: 12/10/85 1400

Date Received: 12/10/85

COD	113.	mg/L
Conductivity	550.	umhos
TOC	49.	mg/L
TOX*		

*Laboratory results not available at this writing. Samples lost in transit from main laboratory to reference laboratory. Sample split being resubmitted for TOX analyses.

Toni Gartner

aqualab inc.
3545 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Chris Berndt
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61108

3 January 1986
Sample No. 37825

SAMPLE DESCRIPTION: W1
P.O. 82634
Date Taker: 12/10/85 1400

Date Received: 12/10/85

VOLATILE COMPOUNDS

ug/L	Compound	ug/L	Compound
<100.	Acrolein	<5.	1,2-Trans-Dichloroethene
<100.	Acrylonitrile	<5.	1,2-Dichloropropane
<5.	Benzene	<5.	1,3-Dichloropropene
<5.	Carbon Tetrachloride	<5.	Ethylbenzene
<5.	Chlorobenzene	<10.	Methylene Chloride
<5.	1,2-Dichloroethane	<20.	Methyl Chloride
39.	1,1,1-Trichloroethane	<20.	Methyl Bromide
<5.	1,1-Dichloroethane	<10.	Bromoform
<10.	1,1,2-Trichloroethane	<5.	Dichlorobromomethane
<10.	1,1,2,2-Tetrachloroethane	<10.	Chlorodibromomethane
<20.	Chloroethane	<5.	Tetrachloroethene
<50.	2-Chloroethylvinyl Ether	<5.	Toluene
<5.	Chloroform	7.	Trichloroethene
<5.	1,1-Dichloroethene	<20.	Vinyl Chloride

Topi Gartner

Aqualab inc.
3545 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Chris Berndt
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61109

3 January 1986
Sample No. 37826

SAMPLE DESCRIPTION: W2
P.O. 82634
Date Taken: 12/10/85 1430

Date Received: 12/10/85

COD	27.	mg/L
Conductivity	550.	umhos
TOC	8.6	mg/L
TOX*		

*Laboratory results not available at this writing. Samples lost in transit from main laboratory to reference laboratory. Sample split being resubmitted for TOX analyses.

Toni Gartner

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Chris Berndt
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61108

3 January 1986
Sample No. 37826

SAMPLE DESCRIPTION: W2
P.O. 82634
Date Taken: 12/10/85 1430

Date Received: 12/10/85

VOLATILE COMPOUNDS

ug/L	Compound	ug/L	Compound
<100.	Acrolein	<5.	1,2-Trans-Dichloroethene
<100.	Acrylonitrile	<5.	1,2-Dichloropropane
<5.	Benzene	<5.	1,3-Dichloropropene
<5.	Carbon Tetrachloride	<5.	Ethylbenzene
<5.	Chlorobenzene	<10.	Methylene Chloride
<5.	1,2-Dichloroethane	<20.	Methyl Chloride
199.	1,1,1-Trichloroethane	<20.	Methyl Bromide
<5.	1,1-Dichloroethane	<10.	Bromoform
<10.	1,1,2-Trichloroethane	<5.	Dichlorobromomethane
<10.	1,1,2,2-Tetrachloroethane	<10.	Chlorodibromomethane
<20.	Chloroethane	<5.	Tetrachloroethene
<50.	2-Chloroethylvinyl Ether	<5.	Toluene
<5.	Chloroform	<5.	Trichloroethene
<5.	1,1-Dichloroethene	<20.	Vinyl Chloride

Toni Gartner

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Chris Berndt
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61109

3 January 1986
Sample No. 37827

SAMPLE DESCRIPTION: W3
P.O. 82634

Date Taken: 12/10/85 1415

Date Received: 12/10/85

COD	17.	mg/L
Conductivity	550.	umhos
TOC	2.2	mg/L
TOX*		

*Laboratory results not available at this writing. Samples lost in transit from main laboratory to reference laboratory. Sample split being resubmitted for TOX analyses.

Tony Gartner

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Chris Berndt
ROCKFORD PRODUCTS
707 Harrison Ave.
Rockford, Il. 61108

3 January 1986
Sample No. 37827

SAMPLE DESCRIPTION: W3
P.O. 82634
Date Taken: 12/10/85 1415

Date Received: 12/10/85

VOLATILE COMPOUNDS

ug/L	Compound	ug/L	Compound
<100.	Acrolein	<5.	1,2-Trans-Dichloroethene
<100.	Acrylonitrile	<5.	1,2-Dichloropropane
<5.	Benzene	<5.	1,3-Dichloropropene
<5.	Carbon Tetrachloride	<5.	Ethylbenzene
<5.	Chlorobenzene	<10.	Methylene Chloride
<5.	1,2-Dichloroethane	<20.	Methyl Chloride
43.	1,1,1-Trichloroethane	<20.	Methyl Bromide
<5.	1,1-Dichloroethane	<10.	Bromoform
<10.	1,1,2-Trichloroethane	<5.	Dichlorobromomethane
<10.	1,1,2,2-Tetrachloroethane	<10.	Chlorodibromomethane
<20.	Chloroethane	<5.	Tetrachlorcethene
<50.	2-Chloroethylvinyl Ether	<5.	Toluene
<5.	Chloroform	452.	Trichloroethene
<5.	1,1-Dichloroethene	<20.	Vinyl Chloride

T. Gartner

Tom Gartner

aqualab inc.
3548 35th St.
Rockford IL 61109
815-874-2171

ANALYTICAL REPORT

Mr. Chris Beerndt
ROCKFORD PRODUCTS
207 Harrison Ave.
Rockford, IL. 61109

15 January 1986
Sample No. 37825-27

SAMPLE DESCRIPTION: We[illegible] Samples
P[illegible] 82634

Date Taken: 12/10/85

Date Received: 12/10/85

Time-Taken	Sample Description	TOX,mg/L
1400	W1	0.087
1430	W2	<0.005
1415	W3	<0.005

Toni Gartner